

Tetra Tech EM Inc.

7932 Nieman Road + Lenexa, KS 66214 + (913) 894-2600 + FAX (913) 894-6295

Site:	ety Kleen Gord	
	098097351	
Break:	19.1	
Other:		
7	-12 00	

January 12, 1999

Mr. Paul E. Doherty START Project Officer U.S. Environmental Protection Agency Superfund Branch 726 Minnesota Avenue Kansas City, KS 66101

RE:

TDD #9812-0004; RCRA Deferral Sites

Safety-Kleen Corporation, Edwardsville, Kansas

EPA ID# KSD980973515

Dear Mr. Doherty:

Tetra Tech EM Inc. (Tetra Tech) has conducted a file review of the above referenced site and made the following determinations regarding its current status:

Database Status:

In both CERCLIS and RCRIS

CERCLA History:

Discovery - 03/90

Environmental Priority Initiative Preliminary

Assessment (EPI-PA) - 09/90

Responsibility:

U.S. Environmental Protection Agency (EPA) RCRA

Site Description: The facility is a storage area for spent solvents from

off-site immersion cleaners and other industrial processes requiring solvents. Spent solvents are transported biweekly to a Safety-Kleen regeneration facility in Elgin, Illinois. The facility is a permitted

RCRA treatment, storage, and disposal (TSD)

facility.

CERCLA Determination:

In 1990, the EPA field investigation team performed an EPI-PA and submitted a preliminary assessment form (EPA Form 2070-12). The only remedial or removal activity indicated in CERCLIS is the EPI-PA. No other remedial or removal interest is indicated. This site has a Final Strategy Determination indicating no further Superfund interest.

Current Status:

This site has a No Further Remedial Action

Proposed (NFRAP) status under CERCLA. This

determination was made in June 1997.

Recommendations:

The facility ID No. for this site, KSD980973515, is



S00136483 SUPERFUND RECORDS

contains recycled fiber and is recyclable

Mr. Paul Doherty January 7, 1999 Page 2

listed in RCRIS and as an archived CERCLIS site. An incorrect facility number (KSD980973516) is entered in one or more EPA databases which is the likely cause of the facility being listed as not occuring in RCRIS. It is recommended that EPA correct the misentered facility ID in the tracking database.

Remarks:

None.

If you have any questions regarding this site, or would like additional information before considering our recommendations, please contact me at (913) 495-3910.

Sincerely,

David A. Zimmermann Environmental Scientist

cc:

Lisa Gard, UOS

File